Contents

FOREWORD **1**

CHAPTER 1 – INTRODUCTION **2**

1.1 PRODUCT REALIZATION PROCESS 2
1.2 BRIEF HISTORY OF CAD/CAM DEVELOPMENT 3
1.3 DEFINITION OF CAD/CAM/CAE 5
1.3.1 Computer Aided Design – CAD 5
1.3.2 Computer Aided Manufacturing – CAM 5
1.3.3 Computer Aided Engineering – CAE 5
1.4. SCOPE OF THIS TUTORIAL 6

CHAPTER 2 – GETTING STARTED **8**

2.1 STARTING AN NX 12 SESSION AND OPENING FILES 8
2.1.1 Start an NX 12 Session 8
2.1.2 Open a New File 9
2.1.3 Open a Part File 10
2.2 PRINTING, SAVING AND CLOSING FILES 12
2.2.1 Print an NX 12 Image 12
2.2.2 Save Part Files 12
2.2.3 Close Part Files 13
2.2.4 Exit an NX 12 Session 14
2.3 NX 12 INTERFACE 14
2.3.1 Mouse Functionality 14
2.3.2 NX 12 Gateway 17
2.3.3 Geometry Selection 21
2.3.4 User Preferences 22
2.3.5 Applications 25
2.4 LAYERS 26
2.4.1 Layer Control 26

2.4.2 Commands in Layers 27
2.5 COORDINATE SYSTEMS 29
2.5.1 Absolute Coordinate System 29
2.5.2 Work Coordinate System 29
2.5.3 Moving the WCS 29
2.6 TOOLBARS 30
CHAPTER 3 – TWO DIMENSIONAL SKETCHING 33
3.1 OVERVIEW 33
3.2 SKETCHING ENVIRONMENT 34
3.3 SKETCH CURVE TOOLBAR 35
3.4 CONSTRAINTS TOOLBAR 37
3.5 EXAMPLES 40
3.5.1 Arbor Press Base 40
3.5.2 Impeller Lower Casing 45
3.5.3 Impeller 49
3.6 EXERCISES 50
3.6.1 Circular Base 50
3.6.2 Sketching of a Holder 51
CHAPTER 4 – THREE DIMENSIONAL MODELING 52
4.1 TYPES OF FEATURES 52
4.1.1 Primitives 53
4.1.2 Reference Features 53
4.1.3 Swept Features 54
4.1.4 Remove Features 55
4.1.5 Extract Features 55
4.1.6 User-Defined features 56
4.2 PRIMITIVES 56
4.2.1 Model a Block 56
4.2.2 Model a Shaft 58

4.3 REFERENCE FEATURES.....61
4.3.1 Datum Plane.....61
4.3.2 Datum Axis.....62
4.4 SWEPT FEATURES.....63
4.5 REMOVE FEATURES.....68
4.5.1 General Hole.....68
4.5.2 Pocket.....70
4.5.3 Slot.....71
4.5.4 Groove.....71
4.6 FEATURE OPERATIONS.....71
4.6.1 Edge Blend.....72
4.6.2 Chamfer.....72
4.6.3 Thread.....73
4.6.4 Trim Body.....74
4.6.5 Split Body.....74
4.6.6 Mirror.....74
4.6.7 Pattern.....75
4.6.8 Boolean Operations.....76
4.6.9 Move.....76
4.7 EXAMPLES.....78
4.7.1 Hexagonal Screw.....78
4.7.2 Hexagonal Nut.....82
4.7.3 L-Bar.....84
4.7.4 Rack.....88
4.7.5 Impeller.....93
4.8 STANDARD PARTS LIBRARY.....96
4.9 SYNCHRONOUS TECHNOLOGY.....97
4.10 EXERCISES.....101
4.10.1 Rocker Arm.....101
4.10.2 Holder.....101

4.10.3 Impeller Upper Casing 102
4.10.4 Die-Cavity 103

CHAPTER 5 – DRAFTING.....105

5.1 OVERVIEW 105
5.2 CREATING A DRAFTING 106
5.3 DIMENSIONING 112
5.4 SECTIONAL VIEW 115
5.5 PRODUCT AND MANUFACTURING INFORMATION 117
5.6 EXAMPLE.....120
5.7 EXERCISE.....125

CHAPTER 6 – ASSEMBLY MODELING 126

6.1 TERMINOLOGY 126
6.2 ASSEMBLING APPROACHES 127
6.2.1 Top-Down Approach..... 127
6.2.2 Bottom-Up Approach..... 127
6.2.3 Mixing and Matching..... 128
6.3 ASSEMBLY NAVIGATOR.....128
6.4 MATING CONSTRAINTS 129
6.5 EXAMPLE.....129
6.5.1 Starting an Assembly 130
6.5.2 Adding Components and Constraints..... 133
6.5.3 Exploded View..... 141
6.6 EXERCISES 144
6.6.1 Arbor Press..... 144
6.6.2 Butterfly Valve..... 145
6.6.3 Jackscrew 149

CHAPTER 7 – FREEFORMING 151

7.1 OVERVIEW 151

7.1.1 Creating Freeform Features from Points 152
7.1.2 Creating Freeform Features from Section Strings 152
7.1.3 Creating Freeform Features from Faces 153
7.2 FREEFORM FEATURE MODELING 154
7.2.1 Modeling with Points 154
7.2.2 Modeling with a Point Cloud 156
7.2.3 Modeling with Curves 157
7.2.4 Modeling with Curves and Faces 159
7.3 EXERCISES 161
7.3.1 Computer Mouse 161
7.3.2 Sport Water Bottle 161
CHAPTER 8 – FINITE ELEMENT ANALYSIS 163
8.1 OVERVIEW 163
8.1.1 Element Shapes and Nodes 163
8.1.2 Solution Steps 165
8.1.3 Simulation Navigator 166
8.2 SCENARIO CREATION 166
8.3 MATERIAL PROPERTIES 169
8.4 MESHING 171
8.5 LOADS 172
8.6 BOUNDARY CONDITIONS 173
8.7 RESULT AND SIMULATION 174
8.7.1 Solving the Scenario 174
8.7.2 FEA Result 176
8.7.3 Simulation and Animation 178
8.8 EXERCISES 181
8.8.1 Arbor Press Bar 181
8.8.2 Rocker Arm 181
CHAPTER 9 – MANUFACTURING 183

9.1 GETTING STARTED 183
9.1.1 Creation of a Blank 183
9.1.2 Setting Machining Environment 185
9.1.3 Operation Navigator 186
9.1.4 Machine Coordinate System (MCS) 187
9.1.5 Geometry Definition 187
9.2 CREATING OPERATION 188
9.2.1 Creating a New Operation 188
9.2.2 Tool Creation and Selection 189
9.2.3 Tool Path Settings 192
9.2.4 Step Over and Scallop Height 193
9.2.5 Depth Per Cut 194
9.2.6 Cutting Parameters 194
9.2.7 Avoidance 195
9.2.8 Speeds and Feeds 196
9.3 PROGRAM GENERATION AND VERIFICATION 198
9.3.1 Generating Program 198
9.3.2 Tool Path Display 198
9.3.3 Tool Path Simulation 199
9.3.4 Gouge Check 202
9.4 OPERATION METHODS 203
9.4.1 Roughing 203
9.4.2 Semi-Finishing 203
9.4.3 Finishing Profile 206
9.4.4 Finishing Contour Surface 210
9.4.5 Flooring 214
9.5 POST PROCESSING 216
9.5.1 Creating CLSF 217
9.5.2 Post Processing 218